

SLC ...In the Beginning




Aging, constrained facilities drive the need for capital improvements.



Source: Airport records.

Airport Redevelopment Program – Goals and Expectations

- **Address Seismic Risk**
- **Provide Right-Sized Facilities**
- **Solve Operational Problems**
- **Improve Customer Service**
- **Accommodate Growth**
- **Maintain Competitive Cost**
- **Phased Implementation (8 to 10+ years)**



SLC Airport Redevelopment Program



Landside Arrival and Departure



Parking Deck Level 2



Gateway showing Pedestrian Walkway Portal



Terminal Level 3 - Ticketing



The Canyon – Meeter Greet Area and Security Checkpoint



The Plaza



Airside View of The Plaza



Concourse




North Concourse Mini-Plaza



North Concourse Exterior




Phase 1 Construction (2016-2020)



■ Under construction


■ Demolition

Phase 1 Complete and Start of Demolition




Demolition Construction complete

Phase 1 Complete and Start of Demolition




Phase 2 Construction (Start 2021)



Under construction

Current Program Final Phase Completed



Project Statistics

TRP/NCP Trade Staffing 3/22/2019

1,835 Trade Workers on Site

5,446,255 Hours Worked to Date

Contract Local/Non-Local Awarded Statistics

Local Trades	Dollar Value	Trade Count	Percentage
Total Local (Wasatch Front) Contractors	\$1,059,074,695	102	67%
Total Out of State Contractors	\$531,383,212	21	33%
Total Contract Awards	\$1,590,457,907	123	100%

Contract Union/Merit Shop Awarded Statistics

Union Trades	Dollar Value	Trade Count	Percentage
Total Union Contractors	\$610,937,898	31	38%
Total Merit Shop Contractors	\$979,520,009	92	62%
Total Contract Awards	\$1,590,457,907	123	100%

Job Progress Photos – Terminal Building and Gateway



Terminal Plaza Area 'B'



Terminal Canyon High-Bat Scaffolding Section 3



Delta Sky Club at Terminal Area 'B' Level 3




Curtain Wall at Gateway and Pedestrian Bridge


Job Progress Photos – Baggage Handling System




CBIS Terminal Area 'A'



CBRA Bag Inspection Area Terminal Area 'B'



Terminal First Baggage Claim Carousel on Level 2




Curbside Baggage Conveyor Terminal Area 'H' Level 2

Job Progress Photos – South Concourse West



SCW Building Exterior – Areas 'A' through 'H', looking north



SCW Level 2 looking west



SCW Level 2 Area 'H1'

Job Progress Photos – Parking Garage, Roadways, CUP



Parking Garage looking north



Parking Garage NW Stair installation



Elevated Roadway Bridge 2 Deck pour prep

Job Progress Terminal Aerial Photo



Terminal, Gateway, and Elevated Roadway, looking west

Job Progress Photos – North Concourse Steel



North Concourse Steel erection, Sectors 'CN' through 'F' (east end), looking north



North Concourse Steel Erection Topping-out



North Concourse Sector 'B' Level 2 looking east

Job Progress Photos – North Concourse



Mid-Concourse Tunnel Concrete Lid forms



North Concourse Sector 'B' Breezeway



North Concourse Sector 'D' Shallow Underground Piping



Mid-Concourse Tunnel Sector 'CN'